

FLUO TP

THE ONLY PAINT THAT DOES NOT CONTAIN CARCINOGENIC, MUTAGENIC, OR TOXIC COMPONENTS FOR REPRODUCTION

PAINTS THAT RESPECT MEN AND THE ENVIRONMENT

100% USAGE GUARANTEE, NO WASTE

CAN BE USED UP TO -15°C

- The only locking cap
- A particularly robust safety cap (a full aerosol dropped from a height of 1.50m will remain intact)
- No contact with the paint


VERY BRIGHT MARKING AND COVERING CAPACITY IN A SINGLE PASS, HIGHLY FLUORESCENT

7 COLOURS AVAILABLE



7 COLOURS AVAILABLE

INSTRUCTIONS FOR USE



- 1** . Before use : Shake vigorously (balls must be clearly audible)
- 2** . Unlock the aerosol by turning left the safety cap
- 3** . Use Fluo TP® « head down » about 10cm from the support
- 4** . After use, purge « head up » to clean out the valve and the diffuser
- 5** . Lock the aerosol by turning right the safety cap

HEALTH AND SAFETY :


Consult our free safety data sheets on our website www.soppec-inc.com

No paint mist or drips during use


GHS labelling with two pictograms



Carton
Box



Palette Nimp15
100 x 120 cm



76 boxes per pallet of
12 aerosols

PROPERTIES

Coverage capacity : From 2 to 4m², depending on covering power and to the nature of the support (colour, porosity)

Autonomy : 100 meters to have maximal coverage. Allows to realize 150 to 200 meters of marking within the speed of application and of covering wished..

Drying time : About 10 minutes at 20°C
Ideal storage between 15 to 25°C, do not freeze

Shelf life : 4 years warranty

Usable with the gun handle and the one-wheel applicator



SAFETY CAP

FLUO TP is fitted with the patented Soppec «TP» safety cap. The unique design of this cap gives it the following advantages :

- Protection against accidental tripping during transport or handling
- Protection of the user's hands against painting projections
- Easy to use
- The strongest safety cap on the market : No break when a full aerosol falls 1.50m (Test carried out on asphalt)
- A fine and precise spray which allows the realization of clear markings
- Cap denotes colour of the paint.

GENERAL CONDITIONS

- Do not expose to temperatures above 50°C
- Keep away from sources of ignition, heat and sunlight
- Do not smoke
- Do not pierce even after use the aerosol
- Do not burn even after use the aerosol